









EXPLODED VIEW




HARDWARE







A x46  M6x90mm	B x46  	C x47  Ø8x30mm	D x4  M6x80mm	E x1  M6x50mm
F x3  M6x30mm	G x8  	H x21  Ø7x50mm	J x1  Ø7x40mm	K x13  Ø4x20mm
L x62  Ø4x30mm	M x2  	P x2  Ø6 x100mm	Q x 9  	

TOOLS



WARNING







07 x2


09

10


11


13

19 x2



A x20	B x20
	
M6x90mm	






A x26




M6x90mm


B x26




05



E x1  M6x50mm	F x3  M6x30mm	G x4 	H x2  Φ7x50mm	J x1  Φ7x40mm	K x6  Φ4x20mm
L x2  Φ4x30mm					



06




H x12



Φ7x50mm

07



P x2




Ø6 x100mm

H x2



Φ7x50mm

C x4  Ø8x30mm	D x4  M6x80mm	G x4 	H x5  Ø7x50mm
--	---	---	--







K x7



Φ4x20mm

Qx9





L x60



Φ4x30mm

