


















(A) X45	(B) X8	(C) X39	(D) X1	(E) X15	(F) X52
					
$\phi 8 \times 30$	M6*90			M6*70	$\phi 4 \times 30$
(G) X6	(H) X12	(I) X12	(J) X8	(K) X20	(L) X10
					
$\phi 6 \times 90$			$\phi 4 \times 40$	$\phi 3 \times 16$	
(M) X4	(N) X16				
					
	M6*80				




Ax12
Bx8
Cx8




02

Ax7
Ex11
Cx11




03

Ax4
Fx26





04

Ax2
Gx2




05

Ax4
Ex2
Cx2





06

Gx4





Cx2
Ex2





09

I x10






10



11


Hx2

**12**Jx8
I x2




14

Ax8
Cx8
Nx8





15

Kx4
Lx2



16

Ax4
Cx8
Nx8



17

Fx26

