













A x32 	B x4 	C x12 	D x2 	E x6 	F x8 
φ 8*30	M6*90	M6*13		φ 6*90	M6*70
G x26 	H x3 	J x3 	K x14 	L x12 	
φ 4*30	M6*30	M6*20	φ 6*70	φ 4*16	


01

Ax18

 $\phi 8*30$ 

02

Ax14

 $\phi 8*30$ 

03

Bx2



M6*90

Cx2








M6*13

Ex2



φ 6*90





05

Bx2






M6*90

Cx2



M6*13

Ex2

 ϕ 6*90

Fx8



M6*70

Cx8





M6*13

Kx8



φ 6*70




07

Gx26



φ 4*30




08

Ex2



φ 6*90




09

09

Kx2



φ 6*70




10

Kx4



φ 6*70



11

Hx3





M6*30

Jx3



M6*20



12

Lx12



φ 4*16

