


1


Step 1 : 50% tighten
screw at this stage.



!
Longer
side
is the
front.

2


Step 2 : 50% tighten
screw at this stage.




!
Longer
side
is the
front.

3


Step 3 : After all parts are in right
position, then 100% tighten up all
screws before using.



4




A



x4

B



x4

C



x4

D



x4

E



x1