












A x19 	B x4 	C x12 	D x4 	E x9 	F x4
φ 8*30	M6*90		φ 6*90	M6*70	φ 6*60
G x1 	H x1 	J x2 	K x4 	L x26 	
M6*30	M6*20	M4	φ 6*70	φ 4*30	

01

Ax19

 ϕ 8*30




03

Fx2



φ 6*60



04

Gx1




M6*30

Hx1



M6*20



05

05

Cx8



Ex8






Kx2



M6*60

φ 6*70




06

Lx26




φ 4*30



07

F x 2

 $\phi 6 \times 60$ 

08

Kx2




φ 6*70


Ex1



M6*70



Style 1



Style 2

