



1

Step 1 : 50% tighten screw
at this stage.




2

Step 2 : 50% tighten screw
at this stage.




3

Step 3 : After all parts are in right position,
then 100% tighten up all screws before using.



4



A

x4



B

x4



C

x4



D

x8



E

x1

