









A x20 	B x4 	C x12 	D x4 	E x8 	F x4
φ 8*30	M6*90		φ 6*90	M6*60	φ 6*60
G x2 	H x10 	J x8 	K x2 	L x26 	M x2
M6*20	M6*20	M6*40	φ 6*70	φ 4*30	M4

01

Ax20



φ 8*30



02

Bx4



M6*90


Cx4



Dx4



φ 6*90




03

Fx1



φ 6*60



04

Gx2




M6*20

Hx2



M6*20



05

05

Cx8



Ex8






Fx3



M6*60

φ 6*60



Hx8



M6*20

Jx8




M6*40

Kx2



φ 6*70



07

Lx26



φ 4*30

