




A x 40



B x 16



C x 16



D x 16



5MM
E x 1



F x 19



G x 4



H x 17



I x 17



J x 4



4MM
K x 1



L x 1




M x 1





N x 4





O x 1




1




2




3




4





5




6




7





8




9






10




11



12



13



14

