

ASSEMBLY INSTRUCTION

Page 1


MODEL : HMT DT 2020 (HM 308) DRESSING TABLE (MIRROR)

Before you begin, please follow Assembly Instruction carefully. Follow them step by step.

STEP 1


(A) M6 X 50MM JCBC
SCREW - 2 PCS

(D) M4 ALLEN KEY - 1 PC



STEP 2


(B) M4 X 16MM C/B
SCREW - 4 PCS



REMARK : ATTACH PART 3 USING (B) SCREW
AND POZI SCREWDRIVER AS SHOWN.


REQUIRED ASSEMBLY TOOLS :
POZI SCREWDRIVER - 1PC

STEP 3



STEP 4

(C) M4 X 16MM C/B
SCREW - 2 PCS



REMARK : ATTACH PART 4 USING (C) SCREW
AND POZI SCREWDRIVER AS SHOWN.


REQUIRED ASSEMBLY TOOLS :
POZI SCREWDRIVER - 1PC

ASSEMBLY INSTRUCTION

Page 2

MODEL : HMT DT 2020 (HM 308) DRESSING TABLE (MIRROR)


Before you begin, please follow Assembly Instruction carefully. Follow them step by step.




FULL SETUP

PART LIST


1) TABLE LEGS X 2 SETS



4) MIRROR X 1 SET




2) PART A X 1 PC



5) CHROME CAP X 2 PCS




3) TABLE WITH DRAWER X 1 PC



6) METAL JOIN X 2 PCS



HARDWARE LIST




(A) M6 X 50MM JCBC SCREW - 2 PCS



(C) M4 X 16 MM C/B SCREW - 2 PCS



(B) M4 X 32 MM C/B SCREW - 4 PCS



(D) M4 ALLEN KEY - 1 PC